Notification #:	20041026	**Revision:**	1.1	**Page:**	1 of 2

Release Date: November 5, 2004

Effective Date: November 5, 2004

Notification Status: ☒ Advisory ☐ Mandatory ☐ Announcement

Classification: ☒ Firmware ☐ Hardware ☐ Policy/Procedure

Description: NexGen $50 Firmware Versions – DBV-14x

Hardware: DBV-14x All Models

Firmware Version: Multiple, (Reference list on page 2)

Correction:

Correction made to the Checksum of firmware DBV-145-SH, ID-044.

Conditions:

JCM engineering has released new firmware to our OEM partners for the USA NexGen $50 release that occurred on September 28, 2004. This firmware will be released by each OEM to the jurisdictional regulatory agencies for approval on their hardware platforms.

- Added NexGen fifty ($50) USD recognition capabilities.
- Acceptance Security for the fifty ($50) USD has been improved. (2001 series)

Notes:

These firmware versions supercede all previous versions of JCM firmware. JCM recommends that all previous versions of firmware be upgraded to the 3.40-xx series (2.40-xx for ID-024) so that our customers can take advantage of the NexGen $50 and increased Acceptance Security.

Notification #:	20041026	**Revision:**	1.1	**Page:**	2 of 2

Release Date: November 5, 2004

Effective Date: November 5, 2004

Notification Status: ☒ Advisory ☐ Mandatory ☐ Announcement

Classification: ☒ Firmware ☐ Hardware ☐ Policy/Procedure

Description: NexGen $50 Firmware Versions – DBV-14x

Hardware: DBV-14x All Models

Firmware Version: Multiple, (Reference list on page 2)

Firmware Reference List:

DBV-145-SS:

ID	Version	Checksum
022	3.40	9BB0
023	3.40-11	FB7B
044	3.40	CCAC

DBV-145-SU:

ID	Version	Checksum
022	3.40	1070
023	3.40-11	CACD
011	3.40-01	98BA

DBV 147-SS:

ID	Version	CRC
024	2.40-07	1FEA

DBV-145-SH:

ID	Version	Checksum
044P	3.40-04	5C74
044WP	3.40-04	4AAE
011	3.40-01	99B8
044	3.40	83C1
004	3.40-05	E74B

DBV-146-SH:

ID	Version	Checksum
045P	3.40-06	2648
045WP	3.40-06	AE2E