Notification No.: 20140804		Vers	sion: 1.0	Page: 1 of 2		
Release Date: August 04, 2014 Effective Date: August 04, 2014						
Notification Status:		Advisory	Mandatory	Announcement		
Classification:] Firmware	X Hardware	☐ Policy/Procedure		
Description: iPRO-RC Anti-Static Modification						
Hardware: il	iPRO-RC Recycler Assembly		Territory: Countries with Polymer Banknotes			
Interface: N	N/A		Check Sum: N/A			
Firmware Version(s): N/A			CRC (seed = 0000): N/A			

Condition:

JCM Engineering has received reports of Polymer Banknotes sticking together or adhering to the sides of the iPRO-RC Recycler Assembly.

Resolution:

An investigation by JCM Engineering determined that a static charge accumulates on the Banknotes. To dissipate the static, Anti-Static strips should be applied to the RC Center Guides of both RC bins. The Anti-Static Strips should be applied to Seats A, B, and C, as shown in Figures 1 and 2.




Figure 1: iPRO-RC Centering Guide (Left Side)




Figure 2: iPRO-RC Centering Guide (Right Side)

(continued on reverse)



Notification No. : 20140804		rsion: 1.0	Page : 2 of 2			
Release Date: August 04, 2014 Effective Date: August 04, 2014						
Notification Status:	X Advisory	Mandatory	Announcement			
Classification:	Firmware		☐ Policy/Procedure			
Description: iPRO-RC Anti-Static Modification						
Hardware: iPRO-RC Re	ecycler Assembly	Territory: Countries with Polymer Banknotes				
Interface: N/A	N/A		Check Sum: N/A			
Firmware Version(s): N/A		CRC (seed = 0000): N/A				

Resolution (cont'd):

- EDP #221278 iPRO Anti-Static Strip, Seat A (two required for each RC Centering Guide).
- EDP #221279 iPRO Anti-Static Strip, Seat B (two required for each RC Centering Guide).
- EDP #221280 iPRO Anti-Static Strip, Seat C (one required for each RC Centering Guide).

Figure 3 (below) displays the proper installation of the RC Centering Guides in the iPRO-RC chassis. Contact your local JCM Customer Service Representative to arrange for service/repair.




Figure 3: iPRO-RC Assembly (Bin 1 & Bin 2 Centering Guides Installed)

Note:

The intent of this announcement is to accurately reflect information available as of this writing. This information is subject to change without notice. Please contact your local JCM Sales Representative or JCM Customer Service for additional information.