

Notification №.: 20120326-2		Version: 1.0	Page: 1 of 1
Release Date:	March 26, 2012	Effective Date:	March 26, 2012
Notification Status:	Advisory	Mandatory	Announcement
Classification:	⊠ Firmware	Hardware	Policy/Procedure
Description:	Firmware Upgrade		
Hardware:	UBA-10/11	Territory:	Canada
Interface:	See Below	Check Sum:	See Below
Firmware Version(s):	See Below	CRC (seed = 0000):	See Below

## **Conditions:**

JCM Engineering received a report from Canada about 3 instances in Ontario (1 on WBA and 2 on UBA) where Customers claimed insertion of a \$100.00 polymer CAN note and received only \$50.00 credit. JCM Engineering immediately conducted a detailed investigation and could not verify any hardware issues or incorrect validation issues.

## **Resolution:**

On March 9, 2012 new firmware was released to our OEM Partners with additional validation countermeasures to further enhance our security as a precautionary effort.

Model/Country	ID	<b>Old Version</b>	New Version	Checksum	CRC
UBA 10/11 - CAN	ID-024	2.10-17	2.11-17	6D43	673B
UBA 10/11 - CAN	ID-003	2.10-31	2.11-39	1EF3	56DD

## Notes:

The intent of this announcement is to accurately reflect information available at the time of this writing. This information can change or be modified at any time with no formal notification requirements. Please contact your local JCM Sales Representative or JCM Customer Service at (800) 683-7248 for additional information.

JCM Global Corporation • 925 Pilot Road • Las Vegas, Nevada 89119 Phone: 800-683-7248 or 702-651-0000 • Fax: 702-644-5512 Email: <u>sales@jcmglobal.com</u> **JCM EMEA** • Mundelheimer Weg 60 D-40472 • Dusseldorf, Germany Tel 49-211-530645-0 • Fax 49-211-53064545 Email <u>sales@jcmglobal.eu</u>